


# City of Lake Forest Bicycle Master Plan

## Community Workshops

## Discovered Areas Hazardous to Cyclists



### Summary of Identified Hazards

#### Downtown Lakeforest:

- Bike Trail goes through parking lot
- Railroad crossings
- Limited access to stores on Western Ave and Market Square
- Limited Trail Access
- Lack of bike parking

#### Deerpath:

- Street is Narrow
- Number of curbcuts and driveways
- Intersection with Route 41
- Congestion at Deerpath Middle School

#### North Shore Bike Trail (Lake Bluff):

- Number of curbcuts and driveways
- Intersections with major roads
- Overhanging bushes

#### Route 60:

- High traffic volume
- Narrow shoulder at overpass

#### Route 41 Intersections:

- Deerpath/Overpass
- Old Elm
- Westleigh Rd

#### Waukegan Rd:

- Intersections and crossings
- Poor condition of roadway
- Limited access from the east

#### Everett/Old Elm

- Intersections with major streets
- Visibility of trail connections
- Difficult access to signed route